

Name of work : Repairs to radiator assly, coloring, branding & seat cushioning of JCB JS 80 No 109482

Sr. No.	Description	Qty	Unit
1	2	3	4
A	Repairs & reconditioning to Radiator assly by removing old damaged radiator core assly by providing fitting new radiator core assly as per OEM Specification given below		
1	Radiator core assly 332/7614	1	No
2	Replacing new radiator core by removing and refitting the to and bottom	1	Job
B 1	Cabin door removing cutting rusted portion, new sheet fitting with welding including denting & Patching wit fitting new hinges etc. /No.	1	Job
2	Complete vehicle old paint removing by scrapping with caustic soda, wire brush etc. Putty filling, applying one coat of red oxide primer, applying two coats of synthetic enamel paint of approved shade & quality to load body, chassis, cabin (Job With Material)	1	Job
1	Branding on vehicle and front & rear number plate, stop plate painting.	1	Job
2	Complete seats & back rests cushioning with coir foam 4" with U foam 2" with best quality rexine cover (Job With Material)	1	Job

[Handwritten Signature]

Deputy Engineer
Mechanical Subdivision No.2
Osmanabad