


ENQUIRY

Name of work : **Repair & reconditioning of Steering assly ,Clutch assly & complete servicing of Mahindra Bolero No. MH 25 P 5122**

Sr. No.	Description		Qty	
	Repair & recoditioning to Steering Assly ,Clutch Assly & flooring of Mahindra Bolreo No. MH 25 P 5122 by opening Clutch unit & Steering unit , dismantling, checking, overhauling by replacing unservicable spares with new spares as per OEM specifications etc complete.Also Complete servicing of machine at periodic interval including applicable changing of fuel filter, engine oil filter			
A	Cost of Spares Charges			
1	0801CA0032N	CLUTCH COVER ASSY	1	No
2	0801BA0285N	CLUTCH DRIVEN PLATE ASSY	1	No
3	0802CAA03740N	CLUTCH RELEASE BEARING	1	No
4	0802CA1770N	CLUTCH RELEASE FORK	1	No
5	0802CAA05301N	MASTER CYLINDER CLUTCH	1	No
6	1102AAA01890N	STEERING GEAR ASSY	1	No
7	0080656	UNIVERSAL JOINT @ STRG.	2	No
8	1104AAA04020N	SHAFT INTERMEDIATE	1	No
9	9420000073	OIL FILTER CARTRIDGE (OPTIONAL	1	No
10	1001CAA15521N	FUEL FILTER ASSY	1	No
B	Cost of Labour Charges			
1	C / 01	Clutch unit complete dismantling, leaning, checking, overhauling by replacing necessary parts	1	Job
2	S / 01	Steering unit overhauling	1	Job
3	S / 06	Wheel alignment	1	Job
4	E/67	Complete servicing of machine at periodic interval including applicable changing of fuel filter, engine oil filter, filters of hydraulic, transmission,	1	Job



G S Giram
Deputy Engineer
Mech. Sub Division (L.T.P)
Latur