

Work Details

Name of work :- Repairs to Main, Arm Short Assembly & Pilot Pipping of TATA Hitachi 120 No. 51578.

Sr. No.	Description		Qty	Unit	Rate Rs	Amount
1	2	3	4	5	6	7
	Repairs to Main, Arm Short Assembly & Pilot Pipping of TATA Hitachi 120 No. 51578. by way of Supplying following spares parts as per OEM Specification & part number given below.					
A	Cost of Spares Charges					
1	4296276	Hose	1	No.		
2	4285464	Hose	2	No.		
	Total of Spares Rs :-					
B	Cost of Labour Charges					
1	Removing & refitting high pressure hose assly. (H/06)		3	Job		
	Total of Labour Rs :-					
	Total Spares+Labour Rs :-					
	CGST 9 % Rs :-					
	SGST 9 % Rs :-					
	Grand Total Rs :-					
	Round Off Rs :-					



(S.S.Garad)

Deputy Engineer

Mechanical Subdivision No. 3,
Dharashiv