

### WORK DETAILS

*Name of work : Repair to Pilot (3,6,7,8 & 9) Piping of Tata Hitachi Zx120-52473.*

| Sr. No. | Part Details   |                  | Qty | Rate | Amount |  |
|---------|--|------------------|-----|------|--------|--|
|         | Part Number  | Description      |     |      |        |  |
|         | Repair to Pilot (3,6,7,8 & 9) Piping of Tata Hitachi Zx120-52473 by way of supplying Following Spare parts as per OEM Specification & part number given below. |                  |     |      |        |  |
| A       | Providing & fitting following spares as per OEM Specification  |                  |     |      |        |  |
| 1       | 4607398  | PIPE             | 1   | No   |        |  |
| 2       | 4453229  | HOSE (A)         | 1   | No   |        |  |
| 3       | 4426611  | HOSE PLASTIC (J) | 1   | No   |        |  |
| 4       | 4426612  | HOSE PLASTIC (K) | 1   | No   |        |  |
| 5       | 4446905  | HOSE             | 1   | No   |        |  |
| 6       | 4607399  | PIPE             | 1   | No   |        |  |
| 7       | 4426610  | HOSE PLASTIC (I) | 1   | No   |        |  |
| 8       | 4442766  | HOSE (SA)        | 1   | No   |        |  |
| 9       | 4453226  | HOSE (D)         | 1   | No   |        |  |
| 10      | 4453228  | HOSE (F)         | 1   | No   |        |  |
| 11      | 4442655  | HOSE             | 1   | No   |        |  |
| B       | <b>LABOUR CHARGES</b>  |                  |     |      |        |  |
| 1       | Removing and refitting high pressure hose assembly   |                  | 11  | Job  |        |  |
|         | <b>GST 18%</b>   |                  |     |      |        |  |
|         | <b>Total Rs</b>  |                  |     |      |        |  |

  
**Deputy Engineer**  
**Mechanical Subdivision, Latur**