

Work Details

Subject :- Repair & Reconditioning to Arm jack (Stick Jack) of TATA Hitachi 120 No. 52466

Sr. No.	Description		Qty	Unit	Rate Rs	Amount
1	2	3	4	5	6	7
	Repair & reconditining to Arm jack (Stick Jack) of TATA Hitachi 120 No. 52466 as per OEM Specification of given below.					
A	Cost of Spares Charges					
1	TC01376/40	Seal Kit	1	No.		
2	TC01376/9	Pipe S/A	1	No.		
	Total of Spares Rs :-					
B	Cost of Labour Charges					
1	Removing bucket/arm/boom jack assly. from machine and refitting after repair. (H/08)		1	Job		
2	Removing & refitting high pressure hose assly (H/06)		1	Job		
	Total of Labour Rs :-					
	Total Spares+Labour Rs :-					
	CGST 9 % Rs :-					
	SGST 9 % Rs :-					
	Grand Total Rs :-					
	Round Off Rs :-					



(S.S. Garad)
Deputy Engineer
Mechanical Sub Division No.3,
Dharashiv