Work Details

Subject :- Repairs to Hydraulic Pump Assembly of TATA Hitachi 120 No. 52466.

Sr. No.	Part Details		Qty	Unit	Rate	Amount
	Part No.	Description				
1	2	3	4	5	6	7
	way dismentaling Hydraulic Pu	embly of TATA Hitachi 120 No. 52466 by mp assly and inspecting, replacing damaged ssembling pump by using new spares as per per given below.				
A	Cost of Spares Charges					
1	2042059	Rotor	1	No.		
2	2044793	Plate Valve	1	No.		
3	4355272	Bearing Needle	1	No.		
4	4463047		1	No.		
	Total of Spares Rs :-					
В	Cost of Labour Charges					
1	Removing Hydraulic / Steering pump from machine & refitting on machine ($H/01$)		1	Job		
	Total of Labour Rs :-					
	Total (Spares+ Labour) Rs :-					
	CGST 9 % Rs :-					
	SGST 9 % Rs :-					
	Grand Total Rs:-					
	Round Off Rs :-					

(S.S. Garad)

Deputy Engineer

Mechanical Subdivision No.3,

Dharashiv