

Work Details

Name of work :- Repairs to Idler Assembly RH Side for TATA Hitachi 120 No. 52466.

Sr. No.	Description		Qty	Unit	Rate Rs	Amount
1	2	3	4	5	6	7
	Repairs to Idler Assembly RH Side for TATA Hitachi 120 No. 52466. by repairs to following spares parts as per OEM Specification & part number given below.					
A	Cost of Spares Charges					
1	3035618	Axle	1	No.		
2	A810060	"O" Rign	2	No.		
3	4153732	Seal Group	2	No.		
4	1020173	Bearing	2	No.		
	Total of Spares Rs :-					
B	Cost of Labour Charges					
1	Dismantling Track chain by removing master pin/No. (UC/01)		1	Job		
2	Removing & refitting of idler assembly (UC/08)		1	Job		
	Total of Labour Rs :-					
	Total Spares+Labour Rs :-					
	CGST 9 % Rs :-					
	SGST 9 % Rs :-					
	Grand Total Rs :-					
	Round Off Rs :-					



(S.S.Garad)
Deputy Engineer
 Mechanical Subdivision No. 3,
 Dharashiv