Work Details

Subject :- Providing & Fitting of Filters, Hoses to TATA Hitachi 120 No. 52466

| Description | | Qty | Unit | Rate Rs | Amount |
|--|---|---|---|-----------------|--|
| 2 | 3 | 4 | 5 | 6 | 7 |
| | | | | | |
| Cost of Spare | | | | | |
| HSN Code | Description | | | | |
| 84212900 | Strainer (Old - 4424867) | 1 | No. | | |
| 84314990 | Element assly Outer (Old No. Y00007394) | 1 | No. | | |
| 84314990 | Eelement assly .Inner (Old - YA00007606) | 1 | No. | | |
| 84099990 | Filter Oil | 1 | No. | | |
| 48232000 | Element; Filter | 1 | No. | | |
| 48232000 | Element; Filter | 1 | No. | | |
| 84219900 | Primary Fuel Filter | 1 | No. | | |
| 84099990 | Element Filter | 1 | No. | | |
| 984204 | Hose | 1 | No. | | |
| 3103895 | Hose | 1 | No. | | |
| | | | Total | of Spares Rs :- | |
| Cost of Labour | | | | | |
| Removing & refitting high pressure hose assly. | | 2 | Job | | |
| | | | Total o | f Labour Rs :- | |
| Total Spares+Labour Rs :- | | | | | |
| CGST 9 % Rs :- | | | | | |
| SGST 9 % Rs :- | | | | | |
| Grand Total Rs :- | | | | | |
| | 52466 as per OEM Spare HSN Code 84212900 84314990 84314990 48232000 48232000 48232000 84099990 984204 3103895 Cost of Labour | HSN Code Description 84212900 Strainer (Old - 4424867) 84314990 Element assly Outer (Old No. Y00007394) 84314990 Eelement assly .Inner (Old - YA00007606) 84099990 Filter Oil 48232000 Element ; Filter 84219900 Primary Fuel Filter 84099990 Element Filter 984204 Hose 3103895 Hose Cost of Labour | Cost of Spare HSN Code Description 84212900 Strainer (Old - 4424867) 1 84314990 Element assly Outer (Old No. Y00007394) 1 84314990 Eelement assly .Inner (Old - YA00007606) 1 84099990 Filter Oil 1 48232000 Element ; Filter 1 48232000 Element ; Filter 1 84219900 Primary Fuel Filter 1 84099990 Element Filter 1 84099990 Hose 1 Cost of Labour Cost of Labour | Cost of Spare | Section Spare Section Sectio |

(S.S. Gorod)

(S.S. Garad) **Deputy Engineer**Mechanical Sub Division No.3,

Dharashiv