

WORK DETAILS

Name of work : Repair to Tata Hitachi Zx120-52473 by replacing BUSH, CYLINDER BOOM (LH) Seal Kit & HOSE etc.

Sr. No.	Part Details		Qty		Rate	Amount
	Part Number	Description				
	Repair to Tata Hitachi Zx120-52473 by way of supplying BUSH, CYLINDER BOOM (LH) Seal Kit & HOSE etc. as per OEM Specification & part number given below.					
A	Providing & fitting following spares as per OEM Specification					
1	4344898	BUSHING	1	No.		
2	4296276	HOSE	1	No.		
3	TC01374/39	SEAL KIT ASSY.	1	No.		
B	LABOUR CHARGES					
1	Removing bucket/arm/boom jack assly. from machine and refitting after repairs		1	Job		
2	Removing and refitting high pressure hose assembly		1	Job		
GST 18%						
Total Rs						



**Deputy Engineer
Mechanical Subdivision, Latur**