


Work Details

Name of work :- Repair & Reconditioning to Radiator Support Assembly, Fuel Piping Of Of Tata Hitachi 120 H No. 52474

Sr. No.	Description	Qty	Unit	Rate Rs	Amount
1	2	3	4	5	6
	Repair & Reconditioning to Radiator Support Assembly, Fuel Piping Of Tata Hitachi 120 H No. 52474 following spares parts as per OEM Specification of given below.				
A	Cost of Spares Charges				
1	4504198	CLAMP;HOSE 6X1	4	No.	
2	A590916	WASHER;SPRING	2	No.	
3	3088910	STAY	1	No.	
4	4426225	BAND	1	No.	
5	4426044	LOCK	1	No.	
6	4444905	RUBBER	1	No.	
7	2046565	HOSE;WATER	1	No.	
8	4609016	BOLT;SEMS	4	No.	
9	4618712	HOSE;WATER	1	No.	
10	A590912	WASHER;SPRING	2	No.	
11	J931635	BOLT	2	No.	
12	4171509	HOSE;VINYL	1	No.	
13	4429220	TUBE	1	No.	
14	9183734	HOSE;FUEL (Offer- 4295998(1))+4	1	No.	
15	4514700	CLIP;HOSE	6	No.	
16	J011020	BOLT; SEMS	5	No.	
17	4190263	CLIP	1	No.	
18	4190266	CLIP 022.0X2	1	No.	
19	4190277	CLIP	1	No.	
20	4452162	PIPE;FUEL	2	No.	
21	9198774	HOSE;FUEL (Offer 4404755)	1	No.	
22	TE23629	HOSE;FUEL	1	No.	
23	9198775	HOSE;FUEL	1	No.	
24	TE23630	HOSE;FUEL	1	No.	
Total of Spares Rs :-					
B	Cost of Labour Charges				
1	E/46 Radiator chock up removing by cleaning all the tubes, soldering the tubes with top & bottom removing and refitting	1	Job		
2	E/41 Complete fuel line opening, cleaning, checking, brazing and refitting	1	Job		
Total of Labour Rs :-					
Total Spares+Labour Rs :-					
CGST 9 % Rs :-					
SGST 9 % Rs :-					
Grand Total Rs :-					
Round Off Rs :-					


 (P.L.Hadule)
 Deputy Engineer
 Mechanical Subdivision No. 2,
 Dharashiv