


Work Detail's

Name of work :- Repair & Reconditioning to Regulator Assly Of Tata Hitachi 120 H No.52474

Sr. No.	Description		Qty	Unit	Rate Rs	Amount
1	2	3	4	5	6	7
	Repair & Reconditioning to Regulator Assly Of Tata Hitachi 120 H No.52474 following spares parts as per OEM Specification of given below.					
A	Cost of Spares Charges					
1	4179155	SLEEVE	1	No.		
2	4179156	SPOOL	1	No.		
3	4367385	CYL.;LOAD	1	No.		
4	4085607	RING;BACK-UP T2P16	1	No.		
5	4367500	PISTON	1	No.		
6	4424628	SLEEVE	1	No.		
7	4346521	SPOOL	1	No.		
8	4350928	SPRING;COMPRES	1	No.		
9	4150302	O-RING 4DP16	1	No.		
10	4436536	SENSOR; PRESSURE	1	No.		
11	4153095	O RING	1	No.		
12	4451498	CYL.	1	No.		
13	4433327	COVER	1	No.		
14	4436800	PIPE	1	No.		
	Total of Spares Rs :-					
B	Cost of Labour Charges					
1	H/02 Hydraulic pump overhauling		1	Job		
	Total of Labour Rs :-					0.00
	Total Spares+Labour Rs :-					0.00
	CGST 9 % Rs :-					0.00
	SGST 9 % Rs :-					0.00
	Grand Total Rs :-					0.00
	Round Off Rs :-					0.00


 (P.L. Hadule)
 Deputy Engineer
 Mechanical Subdivision No. 2,
 Dharashiv