


Work Detail's

Name of work :- Repair Reconditioning to Topical Cover & Hydraulic Tank Connections Of Tata Hitachi 120 H No.52474

Sr. No.	Description		Qty	Unit	Rate Rs	Amount
1	2	3	4	5	6	7
	Repair Reconditioning to Topical Cover & Hydraulic Tank Connections Of Tata Hitachi 120 H No.52474 following spares parts as per OEM Specification of given below.					
A	Cost of Spares Charges					
1	7040051	DOOR	1	No.		
2	8060810	COVER	1	No.		
3	4334587	BREATHER;AIR (Offer - 4434017	1	No.		
4	A810160	O-RING	1	No.		
5	H4250260	ENG OIL PR SENSOR	1	No.		
6	Z957366	O RING (Offer 957366	1	No.		
7	4438888	PIPE (ALT Part A852422)	1	No.		
9	A852133	ADAPTER;S	3	No.		
10	A852333	ELBOW;S	1	No.		
11	A852232	ELBOW;S	1	No.		
12	962567	O-RING(4509180)	1	No.		
13	A885002	DUMMY PLUG	1	No.		
15	A852334	ELBOW;S	1	No.		
16	962567	O-RING(4509180)	1	No.		
17	A885008	PLUG	1	No.		
18	4506429	O-RING	1	No.		
19	8064356	PIPE;RETURN	1	No.		
20	M341040	BOLT;SOCKET M10X040	2	No.		
21	J021030	BOLT;SEMS;M10 X	2	No.		
22	4190127	CLAMP;PIPE	2	No.		
23	J011270	BOLT;SEMS	2	No.		
	Total of Spares Rs :-					
B	Cost of Labour Charges					
1	A/16 Removing hydraulic tank from machine, cleaning, repairing & refitting		1	Job		
2	H/06 Removing & refitting high pressure hose assly.		1	Job		
3	BD/10 Door locks removing, repairing and refitting. Door adjusting and setting/ No. (Equivalent To Tata LPK2518)		1	Job		
	Total of Labour Rs :-					
	Total Spares+Labour Rs :-					
	CGST 9 % Rs :-					
	SGST 9 % Rs :-					
	Grand Total Rs :-					
	Round Off Rs :-					


 (P.L. Hadule)
 Deputy Engineer
 Mechanical Subdivision No. 2,
 Dharashiv