


Works Deatail's

Name of work : Repairs To Arm Assly Of Tata Hitachi 120 H No.52474

Sr. No.	Description	Part No	Qty	Unit	Rate	Amount
1	2	3	4	5	6	7
	Repairs To Arm Assly Of Tata Hitachi 120 H No.52474 by repairs to following spares parts as per OEM Specification of given below.					
A	Spare Parts					
1	4344898	BUSHING	2	No		
2	4443878	BUSHING	2	No		
3	3089103	PIN	1	No		
4	3089243	PIN	1	No		
5	3089242	PIN	1	No		
6	4435123	PIN;STOPPER	2	No		
7	4276696	O-RING	4	No		
					Total A	
B	Labour Charges					
1	H/08 Removing bucket/arm/boom jack assly. from machine and refitting after repairs		1	Job		
					Total B	
					Total A+B	
					SGST @ 9%	
					CGST @ 9%	
					Say Total	
					Grand Total	


P.L. Hadule
Deputy Engineer
Mechanical Subdivision No.2
Dharashiv