

Works Detail's

Name of work : Repairs to Boom Cylinder Assly RH Side of Tata Hitachi 120H No. 52474

Sr. No.	Description	Qty	Unit	Rate	Amount
1	2	3	4	5	6
A	Repairs and reconditioning to Boom Cylinder Assly RH Side of Tata Hitachi 120H No. 52474 by removing old spares and providing and fitting following new spares as per OEM specification given below.				
1	BOOM CYL. SEAL KIT - TC01374/39	1	No		
2	BUSH -TC01374/7	1	No		
3	PIPE SA - TC01374/8	1	No		
		Total A			
B	Cost of Labour Charges				
1	Removing bucket / arm/ boom jack from machine and refitting after repairs (H/08)	1	Job		
2	Dismantling of jack assly., cleaning, inspection and replacement of seals with test & trial (H/09)	1	Job		
3	Eye end rebuilding & making to STD size (H/10)	1	Job		
4	Cylinder barrel end bushing replacement (H/11)	2	Job		
5	Complete fuel line opening, cleaning, checking, brazing and refitting (E/41)	1	Job		
		Total B			
		Total A + B			
		SGST 9%			
		CGST 9%			
		Grand Total			
		Say Amount			


P.L. Hadule
Deputy Engineer
Mechanical Subdivision No.2
Dharashiv