


Work Details

Name of work :- Repair to Pilot Piping Of Tata Hitachi 120 H No.52474

| Sr. No. | Description | | Qty | Unit | Rate Rs | Amount |
|----------------------------------|---|------------------|-----|------|---------|--------|
| 1 | 2 | 3 | 4 | 5 | 6 | 7 |
| | Repair to Pilot Piping Of Tata Hitachi 120 H No.52474 following spares parts as per OEM Specification of given below. | | | | | |
| A | Cost of Spares Charges | | | | | |
| 1 | 4453231 | HOSE(H) | 1 | No. | | |
| 2 | 4453230 | HOSE(G) | 1 | No. | | |
| 3 | 4450443 | HOSE(B) | 1 | No. | | |
| 4 | 4453229 | HOSE(A) | 1 | No. | | |
| 5 | A852223 | ELBOW;S | 4 | No. | | |
| 6 | 4438290 | HOSE;PLASTIC(P3) | 1 | No. | | |
| 7 | 4438288 | HOSE;PLASTIC(T6) | 1 | No. | | |
| 8 | 4351175 | HOSE | 1 | No. | | |
| 9 | 4427838 | HOSE;PLASTIC | 1 | No. | | |
| 10 | 4445718 | HOSE;PLASTIC(DG) | 1 | No. | | |
| 11 | 4445799 | HOSE;PLASTIC(DF) | 1 | No. | | |
| 12 | 4427839 | HOSE(SJ) | 1 | No. | | |
| Total of Spares Rs :- | | | | | | 0.00 |
| B | Cost of Labour Charges | | | | | |
| 1 | H/06 Removing & refitting high pressure hose assly. | | 11 | Job | | 0.00 |
| Total of Labour Rs :- | | | | | | 0.00 |
| Total Spares+Labour Rs :- | | | | | | 0.00 |
| CGST 9 % Rs :- | | | | | | 0.00 |
| SGST 9 % Rs :- | | | | | | 0.00 |
| Grand Total Rs :- | | | | | | 0.00 |
| Round Off Rs :- | | | | | | 0.00 |


 (P.L.Hadule)
 Deputy Engineer
 Mechanical Subdivision No. 2,
 Dharashiv