

Work Details

Name of work : Repair to Main (1,4 & 5), Pilot (4) Piping of TATA Hitachi 120 No. 52475.

Sr. No.	Part Details		Quantity / Unit		Rate	Total
	Part Number	Description				
	Repair to Main (1,4 & 5), Pilot (4) Piping of TATA Hitachi 120 No. 52475. by way of supplying Following Spare parts as per OEM Specification & part number given below.					
A	Providing & fitting following spares as per OEM Specification					
1	4203129	HOSE	1	No		
2	4192047	HOSE	1	No		
3	8080641	PIPE	1	No		
4	8077223	PIPE	1	No		
5	4285464	HOSE	2	No		
6	4445676	HOSE	1	No		
Total of Sopare Rs :						
B	Labour Charges (as per Mechanical Job work Schedule Rate 2019-2020) :					
1	Removing and refitting high pressure hose assembly. (H/06)		7	No		
	Total of Labour Rs :					
	Total of Spares + Labour Rs :					
	CGST 9% Rs :					
	SGST 9% Rs :					
	Grand Total Rs :					
	Round Off Rs :					



(S.S. Garad)
Deputy Engineer
 Mechanical Sub Division No.3,
 Dharashiv