

Work Details

Name of work :- Repairs to Hydraulic Pump Assembly to TATA Hitachi 120 No. 52475.

Sr. No.	Description		Qty	Unit	Rate Rs	Amount
1	2	3	4	5	6	7
	Repairs to Hydraulic Pump Assembly to TATA Hitachi 120 No. 52475. by repairs to following spares parts as per OEM Specification & part number given below.					
A	Cost of Spares Charges					
1	2042059	Rotor	1	No.		
2	2044793	Plate Valve	1	No.		
3	4355272	Bearing Needle	1	No.		
4	4463047	Seal Kit	1	No.		
	Total of Spares Rs :-					
B	Cost of Labour Charges					
1	Removing Hydraulic Pump from machine & fitting after repair work.		1	Job		
	Total of Labour Rs :-					
	Total Spares+Labour Rs :-					
	CGST 9 % Rs :-					
	SGST 9 % Rs :-					
	Grand Total Rs :-					
	Round Off Rs :-					



(S.S.Garad)

Deputy Engineer

Mechanical Subdivision No. 3,
Dharashiv