

Work Details

Name of work :- Repairs to Hydraulic assly & Water Pump Assembly of TATA Hitachi 120 H Ex No. 52475

Sr. No.	Part No.	Description	Qty	Unit	Rate Rs	Amount
1	2	3	4	5	6	7
		Repairs to Water Pump Assembly of TATA Hitachi 120 H Excavator No. 52475 as per OEM Specification given below.				
A	Cost of Spares Charges					
1	4440813	Fan Belt (Old - 4448370)	1	No.		
2	897253-0281	Pump Assly Water Pump	1	No.		
3	9149507	Hose	1	No.		
	Total of Spares Rs :-					
B	Cost of Labour Charges					
1	Replacing water pump assembly.		1	Job		
2	Removing & refitting high pressure hose assly.		1	Job		
	Total of Labour Rs :-					
	Total of Spares + Labour Rs :-					
	CGST 9 % Rs :-					
	SGST 9 % Rs :-					
	Grand Total Rs :-					
	Round Off Rs :-					



(S.S. Garad)
Deputy Engineer
 Mechanical Sub Division No.3,
 Dharashiv