

Work Details

Name of work :- Repair & Reconditioning to Engine Foundation of TATA Hitachi 120 H No. 52475

Sr. No.	Description	Qty	Unit	Rate Rs	Amount
1	2	3	4	5	7
	Repair & Reconditioning to Engine Foundation of TATA Hitachi 120 H No. 52475 following spares parts as per OEM Specification of given below.				
A	Cost of Spares Charges				
1	4334526	RUBBER	2	No.	
2	4086894	WASHER 04.5X015X036	2	No.	
3	A590914	WASHER;SPRING;M	4	No.	
4	J950014	NUT;M14 X 2	4	No.	
5	4428242	STOPPER	2	No.	
6	4366699	STOPPER	2	No.	
7	4426637	Rubber (Old - 4448739)	2	No.	
8	4436537	SENSOR; THERMO	1	No.	
9	4437177	BOLT M16X260	1	No.	
10	J921612	BOLT M16X170	1	No.	
11	4333700	HOSE	1	No.	
	Total of Spares Rs :-				
B	Cost of Labour Charges				
1	E/40 Engine foundation replacing per No.		1	Job	
2	H/06 Removing & refitting high pressure hose assly.		1	Job	
	Total of Labour Rs :-				
	Total Spares+Labour Rs :-				
	CGST 9 % Rs :-				
	SGST 9 % Rs :-				
	Grand Total Rs :-				
	Round Off Rs :-				



(S.S.Garad)

Deputy Engineer

Mechanical Subdivision No. 3,
Dharashiv