

WORK DETAILS

Name of work : Repairs to Hoses Assly for TATA Hitachi 120 H No.52806

Sr. No.	Part Details		Qty		Rate	Amount
	Part Number	Description				
	Repairs to TATA Hitachi 120 H No.52806 by way supplying hoses as per OEM Specification & part number given below.					
A	Providing & fitting following spares as per OEM Specification					
1	4354467	Hose	1	No.		
2	4442655	Hose	1	No.		
3	4450443	Hose	1	No.		
4	4453230	Hose	1	No.		
B	LABOUR CHARGES					
1	Removing & refitting high pressure hose assly.		4	Job		
					GST 18%	
					Total Rs	


Deputy Engineer
Mechanical Subdivision, Latur