

### WORK DETAILS

*Name of work : Repair to Pilot (3,6,7,8 & 9) Piping of Tata Hitachi Zx120-52806.*

Sr. No.	Part Details		Qty	Rate	Amount	
	Part Number	Description				
	Repair to Pilot (3,6,7,8 & 9) Piping of Tata Hitachi Zx120-52806 by way of supplying Following Spare parts as per OEM Specification & part number given below.					
A	Providing & fitting following spares as per OEM Specification					
1	4453229	HOSE	1	No		
2	4453226	HOSE	1	No		
3	4453228	HOSE	1	No		
4	4607398	PIPE	1	No		
5	4607399	PIPE	1	No		
6	4426610	HOSE	1	No		
7	4426611	HOSE	1	No		
8	4426612	HOSE	1	No		
9	4446905	HOSE	1	No		
10	4442766	HOSE	1	No		
11	4442655	HOSE	1	No		
B	<b>LABOUR CHARGES</b>					
1	Removing and refitting high pressure hose assembly			1	Job	
	<b>GST 18%</b>					
	<b>Total Rs</b>					



**Deputy Engineer**  
**Mechanical Subdivision, Latur**