


Name of Work : Repairs to Tata Xenon MH 26 BE 2275

Sr.No	Description of Job	Qty.
A	Repair & reconditioning Rear Suspension assly, stator assly, Electrical systems to Tata Xenon MH 26 BE 2275	
1	289732600104 – Rear shock absorber assly	2 No.
2	28832407102 – First Leaf	2 No.
3	289832407103 – Second leaf	2 No.
4	289832407106 – Fifth Leaf	1 No.
5	289832407109 – Eighth Leaf	2 No.
6	265132204207 – U clamp	4 No.
7	551232103402 - bush	4 No.
8	282632400113 – Shackle assly	4 No
9	269832406701 - Pin	4 No
10	11084110703 – centre bolt	4 No
11	121406061606 – Nylon nut	4 No
12	265115109907 – Switch assly stator	1 No
13	289654400102 – Assly H/L with blinker RH	1 No
14	265954410123 – Assly Rear Stop Lamp LH	1 No
15	265954410124 – Assly rear stop lamp RH	1 No
16	278918130104 – Oil filter	1 No
17	257409110106 – Fuel filter element	1 No
18	253409130254 – Air filter	1 No
19	282647600139 – Fuel line return	1 No
B	Labour Charges	
1	SU/02 – Rear spring leaf assly removing, dismantling, recombining and refitting	2 Job
2	SU/06 – Spring pin and bush replacement	4 Job
3	SU/09 – Shock absorber fitting	2 Job
4	EL/14 – Starter removing and refitting to vehicle after repair	1 Job
5	EL/13 – Starter field coil tapping with material	1 Job
6	EL/12 – Starter solenoid switch replacement	1 Job
7	EL/17 – Starter solenoid switch replacement	1 Job
8	EL/15 – Starter Overhauling	1 Job
9	EL/04 – Complete wiring and loom making	1 Job


Deputy Engineer,
Mechanical subdivision no. 3,
Osmanabad.