


WORK DETAILS

Name of work : *Repair & Reconditioning to Arm Assy of Tata Hitachi EX 350 Hyd Exc No.0402*

Sr. No.	Part Details		Qty		Rate	Amount
	Part Number	Description				
	Repair & Reconditioning to Arm Cylinder Assy of Tata Hitachi EX 350 Hyd Exc No.0402by removing the assly from machine,dismntling checking and removing unserviceable parts & replacing by new spares . Also removing bushing of Arm link assly & replacing by new spares as per OEM Specification					
A	Providing & fitting following spares as per OEM Specification					
1	TD03093	BUSHING	2	No.		
2	4382146	SPACER	2	No.		
3	TD03096	BUSHING	2	No.		
4	TD03095	BUSHING	2	No.		
5	J951020	NUT	6	No.		
6	TD02687	BUSHING	2	No.		
B	LABOUR CHARGES					
1	Removing bucket/arm/boom jack assly. from machine and refitting after repairs.		1	Job		
					GST 18%	
					Total Rs	



Deputy Engineer
Mechanical Subdivision, Latur