

4	YN02C04482P1	Glass	No.	1		0
5	YY12B02188P1	PIN	No.	1		0
6	YY12B02189P1	PIN	No.	1		0
7	LP12B01194P1	Bushing	No.	2		0
8	LP12B01195P1	Bushing	No.	2		0
9	LP64D01016F1	Roller Assembly (Upper)	No.	1		0
A. Total Material charges-						0
GST @ 18 % (SGST 9% & CGST 9%)						0
Total A B1						0
B. Labour Charges-						
1		Dismantling & Refitting Bucket Assembly	Job	1		0
2		Oil/Fuel filter replacing	Job	1		0
3		Track Roller Removing from M/c & Fitting	Job	1		0
B. Total Labour Charges						0
GST @ 18 % (SGST 9% & CGST 9%)						0
B. Total Labour Charges						0
Total Rs. (A +B)						0
Final Total amount Rs.						0


 Executive Engineer,
 Mechanical division,
 Swargate Pune

Measurement

Name of Work- Estimate for Repairs to Kobelco SK 140 No. 387 by Changing the Hydraulic Filter Assembly & Pin, Bushing of Bucket Assembly with Test and Trial at site.

Sr. No.	Part No.	Description	Unit	Qty.	Rate	Amount
1	2	3	4	5	6	7
A. Material Charges-						
1	YN50V00025F1	Hydraulic Strainer Suction	No.	1		0
2	YY06H01007D1	HOSE	No.	1		0
3	YN57V00010S002	Element Hydraulic Filter	No.	1		0
4	YN02C04482P1	Glass	No.	1		0
5	YY12B02188P1	PIN	No.	1		0
6	YY12B02189P1	PIN	No.	1		0
7	LP12B01194P1	Bushing	No.	2		0
8	LP12B01195P1	Bushing	No.	2		0
9	LP64D01016F1	Roller Assembly (Upper)	No.	1		0
A. Total Material charges-						0
GST @ 18 % (SGST 9% & CGST 9%)						0
Total A B1						0
B. Labour Charges-						
1		Dismantling &Refitting Bucket Assembly	Job	1		0
2		Oil/Fuel filter replacing	Job	1		0
3		Track Roller Removing from M/c & Fitting	Job	1		0
B. Total Labour Charges						0
GST @ 18 % (SGST 9% & CGST 9%)						0
B. Total Labour Charges						0
Total Rs. (A +B)						0
Final Total amount Rs.						0


 Executive Engineer,
 Mechanical division,
 Swargate Pune