

WORK DETAILS

Name of work : Repair & Reconditioning Center Joint Assy of Tata Hitachi 120 Hydraulic Exc No. 52806

Sr. No.	Part Details		Qty		Rate	Amount
	Part Number	Description				
	Repair & Reconditioning Center Joint Assy Assly of Tata Hitachi 120 Hydraulic Exc No. 52806 by removing the Center Joint Assy assly from machine,dismantling ,checking and removing unservicable parts & replacing by new spares . Also removing bushing of assly & replacing by new spares as per OEM Specification					
A	Providing & fitting following spares as per OEM Specification					
1	4410066	BUSHING	1	No.		
2	4410446	O RING	1	No.		
3	4406165	SEAL OIL	6	No.		
4	3070250	RING	1	No.		
B	LABOUR CHARGES					
1	Center Joint overhauling.(G/12)		1	Job		
12	4333700	HOSE AASY	1	No.		
2	Removing refitting to High Pressure Hose Assy		1	Job		
					GST 18%	
					Total Rs	



**Deputy Engineer
Mechanical Subdivision, Latur**