

Work Detail's

Name of work : Replacing Boom Cylinder Seal Kit & Valve; Pilot Of Tata Hitachi Ex-200 No.8680

Sr. No.	Description	Part No	Qty	Unit	Rate	Amount
1	2	3	4	5	6	7
	Replacing Boom Cylinder Seal Kit & Valve; Pilot Of Tata Hitachi Ex-200 No.8680					
A	Part Of Spares					
1	TD00716/49	KITSEAL	1	No		
2	TD00716/04	H.E.C, BOOOM CYL	1	No		
3	9089808	PUSHER ASSY (Alt 9104360)	1	No		
4	4182067	JOINT SCREW	1	No		
5	M341025	BOLT;SOCKET M10	2	No		
6	4284175	PLATE	1	No		
7	4177896	GUIDESPRING	1	No		
Total A						
B	Cost Of Labour Charges					
1	H/06 Removing & refitting high pressure hose assly.		1	Job		
2	H/08 Removing bucket/arm/boom jack assly. from machine and refitting after repairs		1	Job		
Total B						
Total A+B						
SGST @ 9%						
CGST @ 9%						
Say Total						
Grand Total						


P.L. Hadule
Deputy Engineer
Mechanical Subdivision No.2
Dharashiv