WORK DETAILS

Name of work: Repair & Reconditioning LH Track Adjuster Assly of Tata Hitachi 120 Hyd Exc No.52806

Sr. No.	Part Details					
	Part Number	Description		Qty	Rate	Amount
	Repair & Reconditioning LH Track Adjuster Assly of Tata Hitachi 120 Hyd Exc No.52806 by removing the assly from machine, dismentling checking and removing unservicable parts & replacing by new spares replacing by new spares as per OEM Specification					
A	Providing & fitting following spares as per OEM Specification					
1	4413075	SEAL DUST	1	No.		
2	4357539	NUT	1	No.		
3	3098282	SPRING	1	No.		
4	4360347	O RING	1	No.		
5	4179303	PACKING O RING	1	No.		
6	4182361	RING WEAR	1	No.		
7	4449766	RING WEAR	1	No.		
8	4219356	HOSE AASY	1	No.		
В	LABOUR CHARGES					
1	Dismantling Track chain by removing Master Pin / Master Link bolts.			Job		
1	Repairs to track adjuster/recoil cylinder by replacing seal kit			Job		
1	Reaseembling track chain by fitting master pin		1	Job		
1	Removing & refitting high pressure hose assembly		1	Job		
			1	1	GST 18%	
Total F						

Deputy Engineer Mechanical Subdivision, Latur