

Work Details

Name of work : Repairs to Track Motor Assly RH Side of L&T CK 72 No. 995.

Sr. No.	Part Details		Qty/Unit		Rate	Total
	Repair to Track Motor Assly RH Side of L&T CK 72 No. 995 by replacing the following spares					
A	Cost of Spares Parts					
1	00835904R	Piston Ring	10	No		
2	01226505H	Wear Plate	10	No		
3	00836307E	Circlip	10	No		
4	01639942V	Roller Bearing Assly	12	No		
5	05146212J	Plug Kit	6	No		
6	30046229U	Cover Kit	1	No		
Cost of Spares Rs :						
B	Cost of Labour Charges					
1	Removing and refitting of Track Motor.		1	job		
2	Overhauling of Track Motor by dismantling, cleaning and inspection of parts, reassembling.		1	job		
	Cost of Labour Rs :					
	Cost of Spares+Labour Rs :					
	CGST 9%					
	SGST 9%					
	Grand Total Rs :					
	Round Off Rs :					



(S.S.Garad)

Deputy Engineer

Mechanical Subdivision No. 3,
Dharashiv