

Work Details

Name of work : Repairs & reconditioning to bucket jack assly.of L & T Ck72 No. 995.

Sr. No.	Description		Qty / Unit		Rate	Total
	Repairs & reconditioning to bucket jack assly.of L & T Ck72 No.995					
A	Cost of Spares					
1	300228631	Crome Bush	2	Nos.		
2	302496395	Seal Kit	1	Nos.		
Cost of Spares Rs :						
B	Cost of Labour					
1	Removing bucket/arm/boom jack assly. from machine and refitting after repairs. (H/08)		1	Job		
2	Dismantling of jack assly., cleaning, inspection and replacement of seals with test & tria. (H/09)		1	Job		
	Cost of Labour Rs :-					
	Total of (Spares + Labour) Rs :-					
	CGST @ 9% Rs :-					
	SGST @ 9% Rs :-					
	Grand Total Rs :-					
	Round Off Rs :-					



(S.S.Garad)

Deputy Engineer

Mechanical Subdivision No. 3,
Dharashiv