

Work Details

Name of work : Repairs & reconditioning to final drive assly (L.H. Side) of L&T CK 72 No. 995

Sr. No.	Part Details		Quantity / Unit		Rate	Total
	Part Number	Description				
	Repairs & reconditioning to final drive assly (L.H. Side) of L&T CK 72 No. 995					
A	Providing & fitting new spares parts as per OEM Specification & equivalent to part to given below removing old unservicable spares					
1	201-398-06T	Bearing	1	No		
2	203-460-63L	Bellow Seal	1	No		
3	006-304-12F	O'ring	1	No		
4	201-398-07U	Bearing	1	No		
Cost of Spares Rs.						
B	Cost of Labour Chagges					
1	Dismantaling track chain by removing master pin/No.UC/01		1	Job		
2	Reassembling of track chain & fitting of master pin by hydraulic press. UC/15		1	Job		
	Cost of Labour Rs :-					
	Cost of Spares+Labour Rs :-					
	CGST 9% :-					
	SGST 9% :-					
	Grand Total Rs :-					
	Round Off Rs :-					



(S.S.Garad)

Deputy Engineer

Mechanical Subdivision No. 3,
Dharashiv