

Work Details

Name of work : Repairs to Idler & Carrier Roller Assly of L&T CK 72 No. 995.

Sr. No.	Part Details		Quantity / Unit		Rate	Total
	Part Number	Description				
	Repairs & Idler & Carrier Roller Assly of L&T CK 72 No. 995. by removing Idler & Carrier Roller assly. Dismantling inspacings & replacing unservicable parts by new spares as per OEM specification given satisfactory test & trial @ site.					
A	Spares required for repairs to Idler					
2	Idler 20242383 Q		1	No		
5	Carrier Roller 20242357M		1	No		
6	20130110E Cover for carrier roller		2	No		
Total of Spares Rs :						
B	Cost of Labour					
1	Carrier roller removing from chassis & refitting.		1	Job		
2	Removing & refitting idler assly.		1	Job		
Total of Labour Rs :						
Total Cost of Spares + Labour Rs :						
CGST 9%						
SGST 9%						
Grand Total Rs :						
Round Off Rs :						



(S.S.Garad)

Deputy Engineer

Mechanical Subdivision No. 3,
Dharashiv