

Work Details

Name of work :- Repair & reconditioning to Cabin Colouring & Seat Cushioning of L&T CK 72 No. 995.

Sr. No.	Description	Qty	Unit	Rate Rs	Amount
1	2	3	4	5	6
	Repair & reconditioning to Cabin Colouring & Seat Cushioning of L&T CK 72 No. 995.				
1	Complete cabin removing from chassis & refitting after repair.	1	Job		
2	Cabin foundation all damaged nut bolts & bracket replacing & new foundation & brackets replacing with fitting including welding etc.	1	Job		
3	All cabin doors removing cutting rusted portion, new sheet fitting with welding including denting & patching with fitting new hinges	1	Job		
4	Cabin flooring rusted sheet cutting & new M.S. sheet welding & patching with preparing bottom C type channel support including material.	1	Job		
5	Radiator chock up removing by cleaning all the tubes, soldering the tubes with top & bottom removing refitting.	1	Job		
6	removing & refitting oil cooler	1	Job		
7	Oil cooler tube cleaning	1	Job		
8	Removing hydraulic control valve from machine and refitting after repair	1	Job		
9	Control valve overhauling	1	Job		
10	Repairs to boss by welding by special electrodes & machining to std size / parent size from tail end.	1	Job		
11	Repairs to boss by welding by special electrodes & machining to std size / parent size from head end.	1	Job		
12	Complete vehicle old paint removing by scrapping with caustic soda, wire brush etc putty filling, applying one coat of red oxide primer applying two coats of synthetic enamel paint of approved shed & quality to load body, chassis cabin	1	Job		
13	Complete seat & back rest cushioning with wire foam 4" with U foam 2" with best quality rexine cover.	1	Job		
	Sub Total Rs :-				
	CGST 9 % Rs :-				
	SGST 9 % Rs :-				
	Grand Total Rs :-				
	Round Off Rs :-				



(S.S.Garad)
Deputy Engineer
 Mechanical Subdivision No. 3,
 Dharashiv