

Work Details

Name of work : Repairs & reconditioning to Track Chain Assly R.H. Side of L&T CK 72 No. 995.

Sr. No.	Part Details		Qty / Unit		Rate	Total
	Providing & fitting following spares parts as per OEM specification & equivalent to part no given below.					
A	Cost of Spares					
1	202 423 79 L	Track Link RH	8	No		
2	202 423 81 H	Track Link Master RH	2	No		
3	201 293 26 C	Track Bush	9	No		
4	201 273 29 G	Track Pin	9	No		
5	201 330 25 K	Bolt	26	No		
6	201 345 51 K	Nut	26	No		
Cost of Spares Rs :						
B	Cost of Labour					
1	Dismantling track chain by removing master pin / master links, bolts etc.		1	Job		
2	Removing & refitting new link bush, pin of track chain/Set (inner & outer)		8	Job		
3	Removing grouser shoe bolts by gas cutting & refitting of grouser shoe with new shoe bolts / Shoe		8	Job		
4	Reassembling of track chain & fitting of master pin by hydraulic press		1	Job		
Cost of Labour Rs :						
Cost of Labour+Spares Rs :						
CGST 9% :						
SGST 9% :						
Grand Total Rs :						
Round Off Rs :						



(S.S.Garad)

Deputy Engineer

Mechanical Subdivision No. 3,
Dharashiv