

Work Details

Name of work : Repairs to Hydraulic System, Bucket, Radiator Assembly of L&T CK 72 No. 997.

Sr. No.	Description	Qty / Unit		Rate	Total
	Repairs to L&T CK 72 No. 997. with material & Cost of Labour Charges as below.				
A	Cost of Spares Charges				
1	Hyd Hose D 01031990	3	No		
B	Cost of Labour Charges				
1	Removing & refitting high pressure hose assly. (H/06)	3	Job		
2	Dismantalling & refitting Bucket assly. (A/20)	1	Job		
3	Reconditioning of bucket by removing damaged side face plates and curved plate by gas cutting and strengthening by fitting new plates by welding. (A/27)	1	Job		
4	Cost of hardened chequered plate (4mm) for above strenthening work	40	Job		
5	Removing Radiator assembly from machine with top & bottom. Removing chokeup of tubes by cleaning all tubes with chemical & special tool. Soldering the leakage tubes with solderise to top & bottom also refitting radiator assembly on machine with test & trial.	1	Job		
6	Branding on machine for and front & rear number with & Departmental ownership etc.	1	Job		
	Cost of Spares+Labour Rs :-				
	CGST @ 9% :-				
	SGST @ 9% :-				
	Grand Total Rs :-				
	Round Off Rs :-				



(S.S.Garad)

Deputy Engineer

Mechanical Subdivision No. 3,
Dharashiv