

Work Details

Name of work :- Repairs to Idler Wheel Assembly RH Side of L&T CK 72 No. 997

Sr. No.	Description		Qty	Unit	Rate Rs	Amount
1	2	3	4	5	6	7
	Repairs to Idler Wheel Assembly RH Side of L&T CK 72 No. 997 by repairs to following spares parts as per OEM Specification & part number given below.					
A	Cost of Spares Charges					
1	202423858	Hub Bushing	1	No.		
2	20242384	End Collar	2	No.		
3	202374178	Plug	1	No.		
4	20346085 K	Seal Ring	4	No.		
5	20333841 B	Bolt	12	No.		
6	20127849 W	Shaft	1	No.		
7	20128414 D	Bush	2	No.		
8	01031905 L	Hose	2	No.		
	Total of Spares Rs :-					
B	Cost of Labour Charges					
1	Dismantling Track chain by removing master pin/ Master Link Bolt.		1	Job		
2	Removing Worn out gun metal bushing of idler assly & fitting new one.		2	Job		
3	Reconditioning to idler outer circumference by welding by special electrone & turning to std size.		1	Job		
4	Removing & refitting of idler assembly. (UC/08)		1	Job		
5	Reassembling of track chain & fitting of master pin by hydraulic press. (UC/15)		1	Job		
6	Removing & refitting high pressure hose assly (H/06)		2	Job		
	Total of Labour Rs :-					
	Total Spares+Labour Rs :-					
	CGST 9 % Rs :-					
	SGST 9 % Rs :-					
	Grand Total Rs :-					
	Round Off Rs :-					



(S.S.Garad)
Deputy Engineer
 Mechanical Subdivision No. 3,
 Dharashiv