WORK DETAILS

Name of work: Repair & Reconditioning Both Sides Recoil Cylinder Assly of JCB JS 140 No 2439384

Sr. No.	Part Details					
	Part Number	Description	Qty		Rate	Amount
	JCB JS 140 No 243 machine, checking	itioning Both Sides Recoil Cylinder Assly of 9384 by removing the cylinder assly from and removing unservicable parts and removing ucing by new spares as per OEM Specification				
A	Providing & fitting following spares as per OEM Specification					
1	JNA0237	Rod	2	No.		
2	JNA0239	Seal	1	No.		
3	JNA0238	Ring	2	No.		
4	1316/0403Z	Screw	4	No.		
5	JRA0233	Valve Check	2	No.		
6	624/80025	Hose	3	No.		
В	LABOUR CHAR	GES			•	
1	Dismantling Track chain by removing Master Pin / Master Link bolts		1	Job		
2	Repairs to recoil cylinder by replacing oil seal. Complete job		1	Job		
3	Reassembling of track chain & fitting of master pin by hydraulic press			Job		
4	Removing & refitting hidden high pressure hose assy.			Job		
	•			•	GST 18%	
Total Rs						

Deputy Engineer
Mechanical Subdivision, Latur