


Work Details

Name of work :- Repairs to Hydraulic System of TATA Hitachi 120 H No. 51578

Sr. No.	Description	Qty	Unit	Rate	Amount
1	2	3	4	5	7
	Repairs Hydraulic System of TATA Hitachi 120 H No. 51578 as per OEM specification given below.				
A	Cost of Spares Charges				
1	4296276	Hose (Arm Group)	1	No.	
2	4260127	Hose (Boom Group)	1	No.	
	Cost of Spare Rs :-				
B	Cost of Labour Charges				
1	Removing & refitting high pressure hose assly.		2	Job	
	Cost of Labour Rs :-				
	Total of (Spares + Labour) Rs :-				
	CGST 9 % Rs :-				
	SGST 9 % Rs :-				
	Grand Total Rs :-				
	Round Off Rs :-				


(S.S. Garad)

Deputy Engineer
Mechanical Subdivision No.3,
Dharashiv