

Enquiry

Name of work : Repair To bucket of BEMl BE-200 excavator No.10076.

Sr. No.	Part Details		Qty.			
	Part Number	Description				
	Repair to bucket of BEMl BE-200 excavator					
A	Providing & fitting following spares as per OEM					
1	155BH12289	Cutter RH	1	No		
2	155BH12272	Cutter left	1	No		
3	160BH31646	Tooth	4	No		
4	924402516	Pin	4	No		
5	BFB1312478	Bolt	8	No		
6	180302430	Nut	8	No		
7	781EC61028	HOSE	1	No		
8	781PH91331	HOSE	1	No		
B	Cost of Labour Charges					
1	A/14	for Repairs to bucket by replacing the teeth for excavators / No.	4	Job		
2	A/15	Replacing side cutter of bucket / No.	2	Job		
3	A/20	Dismantalling & refitting Bucket assy.	1	Job		
4	H/06	Removing & refitting high Pressure Hoses/Pipe assly.	2	Job		
	Total Rs.					
	Add GST					
	Grand Total Rs.					



Deputy Engineer
Mechanical Sub Division (L.T.P)
Latur