

WORK DETAILS

Name of work : Repair to BEML BL9H-Loader No.10560 by replacing Fan, Hoses ,wear pad, Foot str, CAP ASSY & Arm link etc.

Sr. No.	Part Details		Qty		Rate	Amount
	Part Number	Description				
	Repair to BEML BL9H-Loader No.10560 by replacing Fan, Hoses ,wear pad, Foot str., CAP ASSY& Arm link etc. as per OEM Specification & part number given below.					
A	Providing & fitting following spares as per OEM Specification					
1	474BH02213	ARM LINK	1	No		
2	374EI02022	FAN ASSY	1	No		
3	474BH69801	WEAR PAD (ADJ) 474	1	No		
4	474BH69818	WEAR PAD (BOT) 474	1	No		
5	474BH69826	WEAR PAD (TOP) 474	1	No		
6	474CH04021	FOOT STR.	1	No		
7	709121200	CAP ASSY	1	No		
8	474PH03624	HOSE(L=1900)	1	No		
9	474PH03665	HOSE(L=1500)	1	No		
10	474PH05536	HOSE	1	No		
11	474PH05544	HOSE	1	No		
12	474PH05585	HOSE	1	No		
13	CHH2200403	HOSE ASSEMBLY125	1	No		
B	LABOUR CHARGES					
1	Removing and refitting high pressure hose assembly		6	Job		
2	Dismantling fan, guard group & replacing damaged parts by new one		1	Job		
					GST 18%	
					Total Rs	



Deputy Engineer
Mechanical Subdivision, Latur