

INQUIRY

Name of work : Repair to Main (1),Arm Short assly., Pilot (4) Piping of Tata Hitachi Zx120-51573.

Sr. No.	Part Details		Quantity / Unit	Rate	Total
	Part Number	Description			
Repair to Main (1),Arm Short assly., Pilot (4) Piping of Tata Hitachi Zx120-51573 by way of supplying Following Spare parts as per OEM Specification & part number given below.					
A	Providing & fitting following spares as per OEM Specification				
1	4296276	HOSE	1	No	
2	4285464	HOSE	2	No	
Total Rs.					
CGST 9%					
SGST 9%					
Total Rs					
Say Total (A) Rs.					
B	Labour Charges (as per Mechanical Job work Schedule Rate 2019-2020) :				
1	H/06	Removing and refitting high pressure hose assembly	3	No	
Total Rs.					
CGST 9%					
SGST 9%					
Total Rs.					
Say Total (B)Rs.					
Grand Total (A+B)					



(G. S. Giram)

Deputy Engineer,
Mechanical Sub Division(L.T.P.),
Latur