


Work Details

Name of work :Repair & Reconditioning to Electrical System,Front Windshield Glass & Seat Cushioning of Case 770 Loader Backhoe No. MH24 AJ7847

Sr. No.	Part Details		Qty/Unit	Rate	Total
	Part Number	Description			
Repair & Reconditioning to Electrical System,Front Windshield Glass & Seat Cushioning of Case 770 Loader Backhoe No. MH24 AJ7847 by cleaning,inspecting all parts and removing damaged spares and refitting assly. to machine by using new as per O.E.M.specification and part No.given below .					
A	Providing & fitting following spares as per OEM				
1	BU4720007	BATTERY-CABLE-NEGATIVE	1	No	
2	BU4720008	BATTERY CABLE-POSITIVE	1	No	
3	47771661	SWITCH	1	No	
4	47772887	HARNESS-FRONT PANEL	1	No	
5	BU4110138	HARNESS-CABIN	1	No	
6	BU03600133	REAR VIEW MIRROR	2	No	
7	85817210	RH GREY FENDER PANEL	1	No	
8	BU0271104	GLASS FRONT(770-NEW)	1	No	
9	BU0270983	GLASS FRONT LOWER LH	1	No	
10	BU0270998	GLASS FRONT LOWER RH	1	No	
Total of Spares Rs.					0.00
B	Labour Chagges				
1	EL/04	Complete wiring checking & new harness fitting	1	Job	
2	EL/14	Starter removing & refitting after works	1	Job	
3	EL/12	Starter armature rewinding after works	1	Job	
4	EL/13	Starter field coil tapping with material	1	Job	
5	EL/15	Starter overhauling	1	Job	
6	SB/03	Windshield glass repalcement along with rubber	1	Job	
7	SB/04	Complete seat & ack rest cushioning with coir foam 4" with U foam 2" with best quality rexine cover	1	Job	
Total of Labour Rs.					
Total (Spares + Labour) Rs :					
CGST 9%					
SGST 9%					
Grand Total Rs :					
Round Off Rs :					



(G.S.Giram)

Deputy Engineer

Mechanical Subdivision (LTP),
Latur