


Work Details

Name of work :Repairs to Ram Dipper Assembly & Hydraulic Hoses JCB JS 140 No. 2439386.

Sr. No.	Part Details		Qty/Unit	Rate	Total	
	Part Number	Description				
	Repairs To Rams Dipper Assembly Of JCB JS 140 No. 2439386 by removing Rams Dipper Assembly assly. from machine cleaning,inspecting all parts and removing damaged spares and refitting assly. to machine by using new as per O.E.M.specification and part No.given below .					
A	Providing & fitting following spares as per OEM					
1	335/B6884	Seal Kit	1	No		
2	KNJ1920	HOSE	1	No		
3	627/10648	HOSE;HYD 3/4 ST-ST	1	No		
4	JNV1529	HOSE;HYD	1	No		
5	JNV1566	HOSE;HYD	1	No		
	Total of Spares Rs.					
B	Labour Chagges					
1	H/06	Removing & refitting high pressure hose assly.	4	Job		
2	H/08	Removing bucket/arm/boom jack assly. from machine and refitting after repairs	1	Job		
3	H/09	Dismantling of jack assly., cleaning, inspection and replacement of seals with test & trial	1	Job		
	Total of Labour Rs :					
	Total (Spares + Labour) Rs :					
	CGST 9%					
	SGST 9%					
	Grand Total Rs :					
	Round Off Rs :					



(G.S.Giram)
Deputy Engineer
 Mechanical Subdivision (LTP),
 Latur