


Work Details

Name of work :

Repair & reconditioning to Accelerator Pedal, Rear Spring and Shock Absorber, Cushioning and Periodical Maintenance to Mahindra Bolero pickup MH 25 P 5122.

Sr. No.	Part Details		Qty / Unit		Rate	Total
	Part Number	Description				
	Repair & reconditioning to Accelerator Pedal, Rear Spring and Shock Absorber, Cushioning and Periodical Maintanance to Mahindra Bolero pickup MH 25 P 5122. as per OEM Specification & part number given below.					
A	Providing & fitting following spares as per OEM Specification					
1	0317AAB000171N	Accelerator Pedal Assly	1			
2	0313AB1960N	AIR FILTER ASSEMBLY	1	No		
3	0313AC0280N	AIR ELEMENT	1	No		
4	9420000073	OIL FILTER CARTRIDGE (OPTIONAL	1	No		
5	1001CAA15521N	FUEL FILTER ASSY	1	No		
6	1001FAA00561N	TANK MODULE ASSLY	1	No		
7	04D1AAA02680N	LEAF SPRING ASSLY REAR	1	No		
8	0402BA0281N	SHOCK ABSORBER REAR	1	No		
Cost of Spares Rs :						
B	Labour Charges					
1	Radiator chock up removing by cleaning all the tubes, soldering the tubes with top & bottom removing and refitting		1	Job		
2	Complete servicing of machine at periodic interval of 250/500/1000 working Hours including applicable changing of fuel filter, engine oil filter, filters of hydraulic, transmission, steering system etc.		1	Job		
3	Silencer/muffler repairing by removing, cleaning and refitting with welding work		1	Job		
4	Cracked chassis welding with extra channel inner side fitting with nut bolts		1	Job		
5	Complete wiring and loom making		1	Job		
6	Starter armature rewinding with material		1	Job		
7	Rear spring leaf assy. removing, dismantling, recambering and refitting / Assy		1	Job		
8	Shock absorber fitting / N		1	Job		
9	Complete seats & back rests cushioning with coir foam 4" with U foam 2" with best quality rexine cover (Job With Material) (Equivelent)		1	Job		
	Cost of Labour Rs :					
	Cost of Spares + Labour Rs :					
	CGST 18% Rs :					
	Grand Total Rs :					



(G.S. Giram)

Deputy Engineer

Mechanical SubDivision(LTP),

Latur