


Work Details

Name of Work : Repair to Water Pump kit & Servicing to BEML BE-200 Ex.No.10076.						
Sr. No.	Particulars		Qty		Rate	Amount
1	2	3	4	5	6	7
	Repair to Water Pump kit & Servicing to BEML BE-200 Ex.No.10076. by removing unservicable parts & replacing with new parts as per OEM specifications.					
A Cost of Spares Charges						
1	11 Z 7180235	PREFILTER OIL CARTRIDGE	1	No		
2	30 Z 5181045	OIL FILTER CARTRIDGE	1	No		
3	30 Z 7182118	FUEL FILTER SPIN ON MAIN	1	No		
4	155 HS 02074	AIR FILTER ASSY. INNER	1	No		
5	30 Z 1280296	AIR ELEMENT ASSY OUTER	1	No		
6	41 Z 5181063	CENTRIFUGAL FILTER INSERT PAPER	1	No		
7	11Z9900329	WATER PUMP REPAIR KIT	1	No		
8	10Z6180236	HOSE	1	No		
9	781EC61028	HOSE	1	No		
10	CCC0105012	CLAMP	2	No		
	Cost of Spares Rs :					
B Cost of Labours						
1	E/67	Complete servicing of machine at periodic interval of 250/500/1000 working Hours including applicable changing of fuel filter, engine oil filter, filters of hydraulic, transmission	1	job		
2	E/51	Repairing Water Pump by Replacing water pump kit	1	job		
3	H/06	Removing & refitting high Pressure Hoses/Pipe assly.	2	job		
	Cost of Labour Rs :					
	Cost of Spares + Labour Rs :					
	CGST @ 9% Rs :					
	SGST @ 9% Rs :					
	Grand Total Rs :					
	Round Off Rs :					


 Deputy Engineer

Mechanical Sub Division LTP,
Latur