

ENQUIRY

Name of work : *Repair &Reconditioning Boom Assembly of JCB JS 140 Sr No 2439381*

Sr. No.	Part Details		Qty.	
	Part Number	Description		
	Repair & Reconditioning Boom Assly of JCB JS 140 Sr No 2439381 by dismantling from machine, checking and removing unservicable parts and removing worn out bushes and replacing by new spares as per OEM Specification			
A	Providing & fitting following spares as per OEM Specification			
1	811/90376	Pin Pivot Boom Base	1	No
2	811/90580	Pin Pivot	1	No
3	KNV0473	Collar Set	1	No
4	KHV0100	Seal Dust	4	No
6	6009/3827Z	Bolt	1	No
7	173R020VZ	Nut	4	No
8	KNV0534	Shim	2	No
9	JNV1577	Bush Steel	2	No
10	JNV1414	Shim	2	No
B	Cost of Labour Charges			
1	(H/09) Dismantling of Jack assembly cleaning, insperction and replacement of seals with test and trial.		1	Job



G.S.Giram
Deputy Engineer
Mech. Sub Division (L.T.P)
Latur