

## **ENQUIRY**

**Name of work :**      **Repair to R.H. Side Track Roller Assly of JCB JS 140 No 2439386**

| Sr. No. | Part Details                                                                                                                                                                                                                                      |                    | Qty. |     |
|---------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------|------|-----|
|         | Part Number                                                                                                                                                                                                                                       | Description        |      |     |
|         | Repair & Reconditioning R.H. Side Track Roller Assly of JCB JS 140 No 2439386 by dismantling track chain from machine, checking and removing unservicable parts and removing worn out bushes and replacing by new spares as per OEM Specification |                    |      |     |
| A       | Providing & fitting following spares as per OEM Specification                                                                                                                                                                                     |                    |      |     |
| 1       | 331/42460                                                                                                                                                                                                                                         | Track Roller Lower | 2    | No  |
| B       | Cost of Labour Charges                                                                                                                                                                                                                            |                    |      |     |
| 1       | Dismantling Track chain by removing Master Pin / Master Link bolts.(UC/01)                                                                                                                                                                        |                    | 1    | Job |
| 2       | Track Roller Removing refitting to chasis (UC/04)                                                                                                                                                                                                 |                    | 2    | Job |
| 3       | Reaseembling track chain by fitting master pin (UC/15)                                                                                                                                                                                            |                    | 1    | Job |



G.S.Giram  
Deputy Engineer  
Mech. Sub Division ( L.T.P )  
Latur