

MEASUREMENT

Name of work : Repair &Reconditioning Boom Assembly of JCB JS 140 Sr No 2439386

Sr. No.	Part Details		Qty.	Rate	Total
	Part Number	Description			
	Repair & Reconditioning Boom Assly of JCB JS 140 Sr No 2439386 by dismantling from machine, checking and removing unservicable parts and removing worn out bushes and replacing by new spares as per OEM Specification				
A	Providing & fitting following spares as per OEM Specification				
1	811/90376	Pin Pivot Boom Base	1 No		
2	811/90580	Pin Pivot	1 No		
3	KNV0473	Collar Set	1 No		
4	KHV0100	Seal Dust	4 No		
6	6009/3827Z	Bolt	1 No		
7	173R020VZ	Nut	4 No		
8	KNV0534	Shim	2 No		
9	JNV1577	Bush Steel	2 No		
10	JNV1414	Shim	2 No		
	Sub Total A				
	Add GST @ 18 %				
	Total of A Rs.				
B	Cost of Labour Charges				
1	(H/09) Dismantling of Jack assembly cleaning,		1 Job		
	Sub Total B				
	Add GST @ 18 %				
	Total of B Rs.				
	Total (A+B)				
	Say Total				



G.S.Giram
Deputy Engineer
Mech. Sub Division (L.T.P)
Latur