

Abstract

Sr. No	Description of Job	Unit	Rate Rs	Amount
Repairs to Tata Hitachi Ex 200 sr. no.10020				
A				
	Repair to Track motor			
UC/01	Dismantling track chain by removing master pin	1 Job	1478	1478
UC/15	Reassembling of track chain & fitting of master pin by hydraulic press	1 Job	1521	1521
A 11	Overhauling of Track motor by dismantling, cleaning and inspection of parts, reassembling etc	1 Job	3422	3422
	by replacing & fitting following spares -			
TB00656/2	Spindle	1 Nos	161599	161599
TE20555	SEAL KIT	1 Nos	3558	3558
4514259	SEAL;GROUP	1 Nos	23834	23834
A590920	Washer Spring	1 Nos	57	57
4183819	Spacer	1 Nos	576	576
4135227	Plate Thrust	1 Nos	631	631
4139975	Pin	1 Nos	1539	1539
4139998	Pin Spring	1 Nos	297	297
4126657	BRG;NEEDLE	1 Nos	2619	2619
4192982	PLATE;THRUST	1 Nos	425	425
4169567	Pin spring	3 Nos	144	432
4172392	BRG;NEEDLE	3 Nos	2223	6669
4196488	Plate Thrust	6 Nos	546	3276
4172398	Pin	3 Nos	812	2436
4169566	Pin Spring	3 Nos	83	249
4172391	Spacer	1 Nos	488	488
			Labour ammount	6421.00
			Spare Ammount	208685.00
			Labour + Spare	215106.00
			Add GST 18	38719.08
			Labour + Spare	253825.08
			Round Off	253825.00
(Rs. Two Lakh Fifty Three Thousand Eight Hundread Twenty Five Only)				

Allocation:

B1 : 7576.78
 B3: 246248.30
 Total : 253825.08


Sectional ENGINEER,
 Gate Manufacturing & Erection
 Sub Dn No. 1 Akola


DEPUTY ENGINEER,
 Gate Manufacturing & Erection
 Sub Dn No. 1 Akola.

Sanctioned Estimate no. -
 EE/MD/AK/2015 Dt. 12.11.2015
 Sanctd. for Rs. 253825/- Two lakhs fifty three thousand eight hundred twenty five only.


Executive Engineer,
Mechanical Division,
AKOLA