Estimate for Maintenance to Radial Gate 12x8 Mtr - 6 Nos by Applying Anti corrosive blank paint to Emergency gate and flat Oil Paint to its Allied part,Replacement of Old dameged Rubber Seal & Fitting New Rubber Seal to Radial Gate Sise 12x8 - 4 Nos @Wan Project Under Executive Engineer, Akola Irrigation Division,Akola

· Commenter	ag te francis de regiones	icresinary	Married Married Co.	ABSTRACT				
Qty	Unit	(Allest Triul) (Peri	er i tridigi etnimi	Description	•	Rate	Per	Amount
	STORY MARKETON TO	erg	enc	cy Gate Leaf Size 1.2x1.2 mtr - 2 Nos				
1	No	1	196 web	viding and Applying anticorrosive coal tar black pain 1] tin two Coats including surface preparation, chippi ding, cleaning spatters, Dust etc Complete as Directed ow of 1.2 x 1.2 Meter Emergency Gate -2 Set of Wan P	ng the I detail as	89997.24	No	89997.24
-			Sr	Anti Corrosive Coal tar Black Paint	Area Sq M			
****			-	Emergency Gate Leaf	12.95			
- SON		-	-	Blockout	50.000	u makea talgosseneki ila kopeaki	A second service of the	
indonstance		_	-	Diolitott		NATIONAL SERVICES AND THE PROPERTY OF THE PROP	O PORTERIOR AND PROPERTY OF THE PERSON NAMED IN COLUMN 1	Commence of the Section of the Secti
	-	-		a) Total Area For 2 gate :-	125.897			
	-		4	b) Extension platform Total For 2 Gate	24.31			
	_		5	c) Ladder to Extension Platform	19.66			
				Total Area for Anticorrosive Gate (a+b+c)	169.87			
	-		1	Hoist Platform and Bull gear and Other Part	88.92	MODING OFFICE PROPERTY.		
	-	-	2	Sheet Metal Canopy + Railing areg (8.006 m2)	230.568			and the second s
	-	-	-	Total Area For Flat Oil; Paint	327.491			
		en	lac	 	- 4 Nos			
4	No		Di Le ru da .S	smentling of Old damagedside rubber seal of 1 side from a for Rg 12x8 m-01 no. Supplying and fitting new L ty bber seal Conforming to IS 11855-and Dismentling of maged Bottom rubber seal from gate Leaf of RG 12x uppling and Fitting flat type bottom rubber seal Conforms 855-1986 RA-4	rom gate rpe side of old 8 m -01 No	129774.90		519099.60
			1	L type side rubber seal Conforming to IS 11855-	2 No			
	+	$\dagger$	2	flat type bottom rubber seal Conforming to IS 11855- 1986 (Updated ) of Size 90x15 -12.2 mtr	1 No			
			3	Gi Bolt m-20x80 -with doubble washer including Sundry	97 Nos			
		Cle	ani	ing of old Grease, Lubrication & greasing to various pa		Gate (Hoi:	st & RC	; parts)
6	Draining of old oil from RGB and filling with gear oil GX 90 - 13 Core, Cleaning of Gear Train by removing old grease and applying M.P.Grease grade no 150 -17 kg to gear train , pedstal , drum axle , Trunion pin , Locking box and lifting bracket pin etc and refitting of radial gate of 42 MT Cap Hoist -1 No , including cost of material , sundry material and labour charges with leads and lift at site etc complete					6 No	120266.70	

	(	Cleaning and applying cardium compound to Wire Rope of Hoist								
6	No	4	Removing Old Cardium Compound of Wire rope of 42 MT cap hoist - 1 No by cleaning agent & Applying new Cardium Compound (Servocoat 140) - 19 Kg, including cost of material, sundry material and labour charges with leads & lifts at site etc complete, as per drawings, specifications and or instructions of concern in charge	16343.82	No	98062.92				
			Transportation Cost							
1	Trip	5	Distance from wan Project to Akola and Back =180Km Total No. Trips during work= 1 No's.Total KM during work = 90Km Transportation of fabricated structure /steel by 7.5T Cap. Tempo charges.(Charges taken as per Gate Manufacuring CSR 2023-2024, Page No.35 Item No.2)	9233.62	Trip	9233.62				
	. Total									
Add 1% Insurance:										
Add 18% GST:										
Grand Total										
say Rs:										

## Certificates:

- 1) Proposed Shedule of Rates for Gate Repair Activies 2023-24,PWD Civil dsr dated 2023-24,PWD Electrical 2022-23 and JPC steel rates dated 01.04.2025 are taken in to consideration while prepairing the Estimate.
- 2) The required Materials and skilled labours for such type of work are not available within the division, Hence the above work is proposed for outside agency.

stimate prepared by,

(S.S.Chavhan) Asst Engineer II Gate Mfg & Erection Sub Dn No 1 Akola

Estimate cheked by,

Depury Engineer Gate Mfg & Erection Sub Dn No 1 Akola

Sanctioned Estimate No

EE/MD/AK/201.5.

Sarctic for R1 9, 95, 626/- (Rs Nine latch ninety five throusand sixonly, hundred twenty six only)

Executive Engineer Mechanical Division Akola