


Name of Work : Repairs & Reconditioning to Bucket Jack assly of L&T CK
72 Ex. Sr no 995.

Sr.No	Description of Job	Qty.
	Repairs & Reconditioning to Bucket Jack assly of L&T CK 72 Ex. Sr no 995.	
A	Cost of Spare	
1	300228631 - Crome Bush	2 No.
2	302496395 - Seal Kit	1 No.
B	Cost of Labour	
1	Removing Bucket jack assly from machine	1 Job
2	Dismantalling of jack assly cleaning inspection and replacement of seal with test and trail	1 Job
3	Hyd Jack rod bend removing and bend checking.	1 Job
4	Refitting of bucket jack assly on m/c	1 Job


Deputy Engineer
Mechanical Sub division No. 3
Osmanabad